

The Truth About Parking Structure Maintenance How to Protect Your Investment

Atlanta Workplace
Georgia International Convention Center
Friday February 28, 2020



Learning Objectives

- Parking Structures
 - Structure Types
 - Cost Comparison
 - Lifecycle Costs
- Conditions Facing Parking Structures
- Common Deficiencies
- Importance of Routine Maintenance & Timely Restoration

Innovative Engineering, Inc.



Scott L. Weiland PE

- BSCE University of Michigan
- Graduate Studies:
 - San Jose State University
 - Georgia Institute of Technology
- PE in 20 States + PR & Guam
- Parking Consultants Council
- 39 Years in Design and Construction
 - BOMA Georgia Insight magazine
 - Parking Structure Maintenance Part 1 & 2
 - Falling Building Façade Closes Atlanta Streets
 - National Parking Association Parking Magazine
 - Parking Structure Maintenance
 - Parking Today
 - Why is it Raining in my Parking Structure?



Innovative Engineering, Inc.



Trey Thomas PE

- BSCET, Southern Polytechnic State University
- 16 Years in Design and Restoration Engineering
 - Co-author of Parking Structure & Forensic articles
- · Certified in Mold, Lead & Asbestos Surveying
- OSHA Competent Person for Boom & Scissor Lifts
- SPRAT Level 2 Rope Access Technician
- FAA Part 107 Remote Pilot Certificate
- FAA Part 107 Daylight Waiver
- Level I Certified Thermographer
- Expert estimator (within 5% of actual)



Structural Systems

Cast-in-Place Concrete

Precast Concrete

Structural Steel







Cast-in-Place



Advantages

- Flexible Geometry
- Monolithic, Fewer Joints
- Reduced Maintenance Costs
- Longer Life Expectancy
- Higher Durability

Disadvantages

- Higher Initial Investment
- Longer Schedule
- More Labor Intensive
- Difficult Quality Control
- Weather Dependent

Precast Concrete - Advantages



Advantages

- Lower Initial Investment than CIP
- Fabricated in Controlled Plant Environment
- Not Weather Dependent
- Accelerated Construction Schedule

Precast Concrete - Disadvantages



Disadvantages

- May be no local plant
- Geometry not Flexible
- Lower Perceived Ceiling heights
- Shearwalls (Closed In)
- More Joints
- Prone to Thermal Expansion & Contraction Damage
- Corrosion of Steel Embedments
- Higher Maintenance Costs

Structural Steel



Advantages

- Lower Initial Cost than Precast
- Accelerated Construction Schedule
- Fabricated in Controlled Environment
- No Shearwalls (Open)

Disadvantages

- Corrosion Issues
- Higher Maintenance Costs
- Not Suitable for Fire Protection

Typical Annual Life Cycle Costs/Space




Parking Structures



- Not Bullet Proof
- No Protective Skin
- Deterioration Starts Immediately
- Subjected To:
 - Moisture (Rain, Snow, Ice, Deicing Salts)
 - CO₂ Carbonation
 - Extreme Thermal Expansion & Contraction
 - Dynamic Vehicle Loads

Structure Degradation



Irving Texas, O'Conner Ridge Blvd. Collapse




Irving Texas, O'Conner Ridge Blvd. Collapse



- What we know
 - Old Parking Structure
 - Expansive Soils in TX
 - Exterior Columns Leaning
 - Cracks Sealed with Sealant
 - No OSHA Report
 - Demolished

Irving Texas, O'Conner Ridge Blvd. Collapse



Typical Precast Double Tee
 Joist Seat


Common Deficiencies


Number 1 Enemy



WATER

Common Deficiency: Corrosion






A: Spall

B: Crack

C: Corner Spall

D:Delamination

Common Deficiency: Spall & Delamination








Spall


Delamination

Section Loss

Common Deficiency: Ponding




Ponding



Supplemental Drain

Common Deficiency: Failed Joints



 Why is it Raining in my Parking Structure?

Common Deficiency: This is Why



Sealant Failure




Cracks



Expansion Joint Failure

Common Deficiency: Failed Joint Sealant



Drainage & Joint Plan

Precast

- All orthogonal lines are sealant Joints
- Diagonal lines are slope lines

Cast-In-Place Slab

- Expansion joint in middle
- Joint sealant at perimeter and at stair towers

Common Deficiency: Cracks to be Sealed




.013" < Cracks < .035"



Cracks that Leak < .035"

Common Deficiency: Route & Seal



Crack Chasing



Crack Sealant

Common Deficiency: Epoxy Injection





Restorations Inc Engineered þ Photos

Cracks \geq .035"

Inflatable Injection Port

Common Deficiency: Corrosion





A: Spall

B: Crack

C: Corner Spall

D:Delamination

Common Deficiency: Concrete Spalls








Spall

Delamination

Section Loss

Common Deficiency: Exterior Spalls



Spall Over Sidewalk




Spall Size

Common Deficiency: Sounding






Common Deficiency: Last Resort





Traffic Bearing Membrane

Common Deficiency: Better Option



Silane Sealer

- Water Retardant
- Breathable
- Fills Pores of Dense Concrete
- Minimizes penetration of water and chemicals
- Reapply 5 to 10 years

Common Deficiency: Failed Spall Repair





Improper Surface Preparation

Precast Haunch Connection Failure




Precast Beam Haunch



4 Months Later

Precast Haunch Connection Repair



Shoring to Remove Load



Applying Epoxy Bonding Agent


Precast Haunch Connection Finished Repair



Good as New

Common Deficiency: Overloaded – Fire Truck





Broken Precast Spandrel Beam

Common Deficiency: Curbs & Wheel Stops



Broken Curb





Broken Wheel Stop


Precast Shear Transfer Repair



Precast Shear Transfer Repair








Precast Double Tees

Shear Transfer

Repair


Precast Shear Transfer Repair



Saw Cut Slab



Prepared Joint & Biscuit




Repair


Images by V2 Composites


Structural Steel Corrosion




- Steel Protection & Corrosion Issues
- Steel Deck Traps Moisture, Hides Degradation.











Reactive Maintenance





Now Demolished

Maintenance Program: Planning



Parking Facility Maintenance Manual Fifth Edition

Extending the Life of Your Facility Through Site-Specific Maintenance and Repairs



A Publication of the National Parking Association's Parking Consultants Council

Source: National Parking Association

- Pre-Construction Design
- Condition Assessment
- Maintenance Checklist & Schedule
- Inspection Checklists
- Budget

Buying Services - Scope of Work



Buying Services – The Sequence

- Condition Assessment
 - Level I
 - Level II
 - Level III
- Construction Documents
- Bidding & Award
- Resident Engineering

Learning Objectives

- Parking Structures
 - Structure Types
 - Cost Comparison
 - Lifecycle Costs
- Conditions Facing Parking Structures
- Common Deficiencies
- Importance of Routine Maintenance & Timely Restoration

Questions?

Scott L. Weiland PE

Innovative Engineering Inc.
3380 Trickum Road
Bldg. 500, Suite 100
Woodstock, Georgia 30188
sweiland@ieiusa.com
770-517-5507 Ext. 202